

The following exterior features of the Martin/Rogers House, 133 East Ave., are protected by City Ordinance No. 9125, approved April 22, 2008:

- (1) Three-story Shingle style house with wood shingles on second and third levels, and at first level on northeast, northwest, and half of southwest façade.
- (2) Cobblestone first level on half of southwest façade extending along southeast façade.
- (3) Gambrel roof with cross gables on southeast and northwest façades.
- (4) Cobblestone wraparound porch on southwest and northwest façades.
- (5) Cobblestone chimney on northwest façade.
- (6) Beaded board ceiling on wraparound porch.
- (7) Cobblestone porte-cochere with beaded board ceiling and wood band molding on northwest side.
- (8) Wood molding under eave of porch and porte-cochere on southwest and northwest façades.
- (9) Peaked gable on northwest façade with double square windows. Bay window with diamond sashes.
- (10) Cobblestone entry arch on southwest façade with wood front door.
- (11) Bay window with diamond sashes on southwest façade.
- (12) All wood eaves, fascias, and molding between second and third levels.
- (13) All wood trim around windows.
- (14) Third level arched window on southwest façade with diamond and bent line patterned sashes and shingle arch hood.
- (15) Bay window with diamond sashes on southeast façade.
- (16) Dormers with diamond sashes and wood trim.
- (17) One of two cobblestone chimneys.
- (18) Stone lintels and sills on southeast façade on first level and basement windows.
- (19) Two-story bay on southeast façade and third-level balcony with encased railing.
- (20) Palladian window in southeast gambrel gable with diamond sashes and arched shingle pattern above central arch.
- (21) Screened in cobblestone porch on east corner.
- (22) Wood porch on northeast façade with wood trim, posts, railing, floor and steps.
- (23) Windows on third level on northeast façade with four-over-four sashes.
- (24) Brick chimney with stone chimney top on northeast façade.
- (25) Dormer with diamond sashes on northwest façade over cobblestone porch.